1st & final bill

...ork in connection ...ded in the office.

Sub-Division ... ದಿನಾಂಕ. 29.20.ಬಿ

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

225634

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions			Contents	Reference to last Measurement
			Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Name of work:- Improvements of cc drain & covering Slab Bylappa circle left side to Nelamahushwaramma temple road Dasarahalli ward No-15.						
	Estimate Cost:- RS 30.00 lakhs.						
	Job Code:- 015-20-000006, P-code:- 1771						
	NO NO:- EE/DD/W.O/462/2019-20, Dt. 13/12/2019.						
	A.A No:- EE/DD/AS/120/2019-20, Dt. 17/06/2019.						
	T.S No:- EE/DD/TS/108/2019-20, Dt. 03/02/2019.						
	Agency:- Sri. muniraj. Naik.						

ಸಹಾಯಕ ಕಾರ್ಯ ಪಾಲಕ ಅಭಿಯಂತರರು
ಜ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಬಿ.ಬಿ.ಎಂ.ಪಿ.
ಬೆಂಗಳೂರು 560073.

Scanned with CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Abstract.						
Sl. No	Description of Item	unit	Qty		Rate		amount
1	Dismantling of existing Structure.	cum	133.14		1684.00		2332824.00
2.	Earthwork excavation	Cum	367.15		137.00		50300.00
3.	PCC of mix 1:3:6.	Cum	36.72		5421.00		199033.00
6.	TMT bar Fe 500	Tonne	8.78		72326.00		634784.00
4.	RCC of mix 1:1½:3 M20	Cum	110.52		7070.00		781376.00
5	RCC Precast Slab	Sqm	275.82		2208.00		609011.00
7	Disposal of Debris.	Cum	367.15		69.00		25333.00
						Sub Total	2532461.00
						GST 12%	303895.00
							2836356.00

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಜಿ.ಜಿ.ಎಂ.ಪಿ.
ಬೆಂಗಳೂರು-560073

Scanned with CamScanner

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

225635

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work		Dimensions			Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	(Twenty eight lakhs thirty Six thousand three hundred & fifty Six Rupees only.)						
	Certificate: 1) This is Certify that the Contractor has completed the work Satisfactory. 2) The Contractor has cleared the debris from the work spot. 3) The Contractor has used his own vehicles for the conveying the debris. 4) There are No departmental issues for the above work. Contractor						

ಸಹಾಯಕ ಕಾರ್ಯ ಪಾಲಕ ಇಂಜಿನಿಯರರು
ಕ್ಷ ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಪಿ.ಡಬ್ಲ್ಯು.ಎಂ.ಪಿ.
ಬೆಂಗಳೂರು-560073.

Scanned with CamScanner

SUREMENT BOOK

Dimensions				Contents	Reference to last Measurement
Number 3	Length 4	Breadth 5	Depth 6	7	8



M. A. R. 57 (Rule 116)
Measurement Book

No. D 225636

Serial No. .....
Name of work ..... From ..... To .....
Name of Contractor of nature of Agency.....
Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8



ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು 560073.

by cheque No.....

Scanned with CamScanner